


## • Notice •



Conduit Entry should be at opening(s) provided or at location(s) indicated by dimples on outside of enclosure. Conduit hubs must be CSA certified and should be suitable for the application. If required to make field connections to stud type terminals, use hardware provided and assemble as shown.


**Note:** All electrical wiring must be done by a qualified electrician in accordance with local and national electrical codes.



Chore-Time Equipment a Division of CTB, Inc.  
P.O. Box 2000 • Milford, Indiana 46542-2000 • U.S.A.  
Phone (219) 658-4101 • E-Mail: [ctb@ctbinc.com](mailto:ctb@ctbinc.com)

MA1017C  
September 1999

## • Notice •



Conduit Entry should be at opening(s) provided or at location(s) indicated by dimples on outside of enclosure. Conduit hubs must be CSA certified and should be suitable for the application. If required to make field connections to stud type terminals, use hardware provided and assemble as shown.


**Note:** All electrical wiring must be done by a qualified electrician in accordance with local and national electrical codes.



Chore-Time Equipment a Division of CTB, Inc.  
P.O. Box 2000 • Milford, Indiana 46542-2000 • U.S.A.  
Phone (219) 658-4101 • E-Mail: [ctb@ctbinc.com](mailto:ctb@ctbinc.com)

MA1017C  
September 1999

## • Notice •



Conduit Entry should be at opening(s) provided or at location(s) indicated by dimples on outside of enclosure. Conduit hubs must be CSA certified and should be suitable for the application. If required to make field connections to stud type terminals, use hardware provided and assemble as shown.

**Note:** All electrical wiring must be done by a qualified electrician in accordance with local and national electrical codes.



Chore-Time Equipment a Division of CTB, Inc.  
P.O. Box 2000 • Milford, Indiana 46542-2000 • U.S.A.  
Phone (219) 658-4101 • E-Mail: [ctb@ctbinc.com](mailto:ctb@ctbinc.com)

MA1017C  
September 1999