


• Notice •



Conduit Entry should be at opening(s) provided or at location(s) indicated by dimples on outside of enclosure. Conduit hubs must be CSA certified and should be suitable for the application. If required to make field connections to stud type terminals, use hardware provided and assemble as shown.


Note: All electrical wiring must be done by a qualified electrician in accordance with local and national electrical codes.



Chore-Time Group, A division of CTB, Inc.
PO Box 2000
Milford, Indiana 46542-2000 USA
Phone (574) 658-4101 Fax (877) 730-8825
Email: choretime@choretime.com / Internet: www.choretime.com

MA1017D
March 2019

• Notice •



Conduit Entry should be at opening(s) provided or at location(s) indicated by dimples on outside of enclosure. Conduit hubs must be CSA certified and should be suitable for the application. If required to make field connections to stud type terminals, use hardware provided and assemble as shown.


Note: All electrical wiring must be done by a qualified electrician in accordance with local and national electrical codes.



Chore-Time Group, A division of CTB, Inc.
PO Box 2000
Milford, Indiana 46542-2000 USA
Phone (574) 658-4101 Fax (877) 730-8825
Email: choretime@choretime.com / Internet: www.choretime.com

MA1017D
March 2019

• Notice •



Conduit Entry should be at opening(s) provided or at location(s) indicated by dimples on outside of enclosure. Conduit hubs must be CSA certified and should be suitable for the application. If required to make field connections to stud type terminals, use hardware provided and assemble as shown.

Note: All electrical wiring must be done by a qualified electrician in accordance with local and national electrical codes.



Chore-Time Group, A division of CTB, Inc.
PO Box 2000
Milford, Indiana 46542-2000 USA
Phone (574) 658-4101 Fax (877) 730-8825
Email: choretime@choretime.com / Internet: www.choretime.com

MA1017D
March 2019